

TECH TIP


THERMAL FAN CLUTCH DIAGNOSIS

Many times, when an engine overheats, the easy answer is to replace the thermal fan clutch. This usually does not correct the problem of overheating.

To properly diagnose fan clutch issues, you need to understand how it functions. When cooling is not needed, the fan clutch is disengaged. As the pulley spins, typically driven by the belt, the fan is driven at a minimal speed (usually 10 to 20 percent), reducing the drag on the engine. As the coolant heats up, the air passing through the radiator increases in temperature. The hot air passing over the bi-metal spring causes the coil to expand. This moves internal components inside the fan clutch, allowing the silicone fluid to pump into the drive area. Silicone generates friction in the drive area, causing the fan clutch to engage, thus driving the fan to a higher percent of the pulley speed (anywhere between 60-90 percent). Once cooling is achieved, the bi-metal spring contracts, closing off the flow of silicone. This reduces the friction, allowing the fan to spin at a lower percent.

We do not publish the temperature range of the bi-metal spring. This is to make sure that no one attempts to measure the temperature of the air crossing the fan clutch face, which could cause personal injury.

Replace the Fan Clutch and Water Pump at the Same Time



Fan Clutch

Since your fan clutch is connected to your water pump, it's easy to see why you should replace the fan clutch at the same time you change the water pump.

Water Pump

The water pump and fan clutch share a common shaft. When the water pump fails, the fan clutch fails and should be replaced.

Proper Diagnosis Procedure: Start with a cold engine. The thermal fan clutch will be engaged for a short period of time during engine warm up. This length of time depends upon the duty and/or specifications of the vehicle tested. When air temperature is sufficient enough to activate the bi-metal spring, the fan clutch should engage. Air flow is critical; check for any obstructions or limiting factors such as shrouds and air dams present, radiator and condenser are free of debris, the cooling system is properly maintained and the fan blade has no bent/cracked/chipped blades. At cold startup, the pitch of the fan blade controls how fast the clutch disengages.

Lack of disengagement can be an issue as well. Commonly, excessive fan noise is noted by the vehicle occupants, as well as some cooling issues. A fan clutch that will not disengage will continue to try to cool the engine when no longer needed. Care should be taken to ensure the correct fan clutch is installed on the vehicle as each clutch disengages at a specific temperature with a specific fan blade. Hot spots in the radiator, lack of airflow across the bi-metal spring or other airflow obstructions can alter the performance of a fan clutch and cause disengagement issues.